To: Sandoval, Joni[Sandoval.Joni@epa.gov]

From: Ostrander, David

Sent: Tue 7/1/2014 8:58:11 PM

Subject: RE: ERRS 4 QARF for Gold King Mine

Let's use this SOW as a discussion point on what we should do with SOWs.

From: Sandoval, Joni

Sent: Tuesday, July 01, 2014 2:18 PM

To: Ostrander, David

Subject: FW: ERRS 4 QARF for Gold King Mine

This one was relatively painless!

From: Berig, Jennifer

Sent: Thursday, June 26, 2014 3:47 PM

To: Sandoval, Joni

Cc: Himmelbauer, Linda; Hanley, lee

Subject: RE: ERRS 4 QARF for Gold King Mine

Hi Joni,

I reviewed the QARF and SOW for TO 052 Red Arrow Drums and have no comments. You can route for signature.

There is one small clarification on the SOW for TO 051 Gold King Mine that I have attached with track changes (one edit at the bottom of page 3). With this change this QARF and SOW will also be ready for signature.

Please print the SOWs and QARFs (including COR original signatures) for each TO. The routing sheet from WebForms needs to include yourself, me, then Linda as the last concurrence. Once I have the documents, I will have Linda sign and drop the originals by your desk as well as send

you the electronic documents. Let me know if you have any questions.

Thanks!

Jenn

Jennifer Berig, P.E. U.S. EPA Region 8 (8TMS-Q) 1595 Wynkoop St

Denver, CO 80202 Phone: 303-312-6262

E-mail: <u>berig.jennifer@epa.gov</u>

From: Sandoval, Joni

Sent: Wednesday, June 25, 2014 4:32 PM

To: Berig, Jennifer

Cc: Himmelbauer, Linda; Way, Steven

Subject: ERRS 4 QARF for Gold King Mine

Please find the attached QARF and SOW for review and approval! Thank you in advance.

I have the signed one down here, be both of our floor's printers are down.